CUBIC
FEET
AL-800
MAOP 2.0 PSI
AMERICAN
METER COMPANY
WARNING
THE PROPER METHOD FOR PRESSURIZING THIS
METER MUST BE USED:
1. OPEN METER OUTLET VALVE SLOWLY.
2. VERY SLOWLY, CRACK INLET VALVE
UNTIL METER REVOLVES.
3. VERY SLOWLY, OPEN INLET VALVE
FULLY.
FAILURE TO COMPLY WITH THIS PROCEDURE
WILL RESULT IN DAMAGE TO THIS METER.
REFER TO INSTRUCTION BOOKLET FOR
MORE DETAILED INSTRUCTIONS OR IF
YOU ARE USING A BYPASS METER SET.