

Kangaroo Media Inc

Address: 20865 Ch de la Cote nord, suite 101 Boisbriand, Quebec, J7E 4H5 Canada

Tel.: 450-595-2023

Fax: 450-595-2023

E-mail: ptremblay@fanvision.com

2020-01-21

Federal Communications Commission

Authorization and Evaluation Division,

7435 Oakland Mills Road

Columbia, MD 21046

USA

Re: SWITCH (FCC ID: 2ATRP-SWITCH)

Gentlemen:


The scanner receiver equipment meets the requirements of the FCC Rules, 15.121 (a). Compliance is achieved through the following methods:

The scanner receiver in this equipment is incapable of tuning, or readily being altered, by the

User to operate within the frequency bands allocated to the Domestic Public Cellular Telecommunications Service in Part 22. Blocking of the cellular frequencies is implemented

in the firmware of the unit's main control central processing unit (CPU). Coverage of 824 -849 MHz and 869 - 894 MHz is completely blocked, since it is done in the microprocessor, and cannot be re-enabled by any user-accessible procedure, including diode, resistor, or jumper changes, nor by connection of any external device such as a personal computer, nor by installation of any "special" enabling semiconductor device. The scanning receiver is designed so that the tuning, control and filtering circuitry is inaccessible.

Signature



Sincerely,

Kangaroo Media Inc

Pascal M. Tremblay

Project Manager