





ATTACHMENT G – SCHEMATIC DIAGRAM(S)



IMPORTANT SAFETY NOTICE
THE SHOWN MAIN OF THIS SCHEMATIC
IS A WARNING OF THE DANGERS OF
ELECTRICITY. IT IS ESSENTIAL THAT ONLY
MANUFACTURER SPECIFIED PARTS BE USED FOR
THE CRITICAL COMPONENTS IN THE SHOWN MAIN.

