

Keeson Technology Corporation Limited  
No.1508, Xiushui Road, WangJiangjing Town, Xiuzhou District, Jiaxing City, Zhejiang Province, China

## Family Certification Attestation Letter

2/26/2026

Nemko Canada Inc  
303 River Road  
Ottawa  
K1V 1H2  
Canada

ATTN.: Reviewing Engineer

FCC ID: 2AK23RC302BD  
Models: RC302B、RC302C、RC302D


We hereby request Family Certification for the above mentioned HVINS/Models based on them being electrically, these differences do not affect RF performance.

The specific differences are as follows:

1. In terms of product functions and appearance, The RC302B remote control lacks 3 function buttons compared to the RC302D remote control. The RC302B remote control also lacks the surface-mount resistors and surface-mount diodes located at these 3 function buttons.
2. In terms of product functions and appearance, The RC302C remote control lacks 1 function buttons compared to the RC302D remote control. The RC302C remote control also lacks the surface-mount resistors and surface-mount diodes located at these 1 function buttons.
3. The colors of RC302B, RC302C, and RC302D will vary.
4. The structures of RC302B, RC302C, and RC302D are the same.

therefore the test performed on the model RC302D.

Signed:



Printed name: Sam Xu  
Title: Certification Manager  
Date: Keeson Technology Corporation Limited