





Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Appendix A3: Minimum 6dB Bandwidth

Test Result B4

Test Mode	Antenna	Frequency[MHz]	6db EBW [MHz]	FL[MHz]	FH[MHz]	Limit[MHz]	Verdict
11A	Ant1	5745	16.360	5736.760	5753.120	0.5	PASS
11A	Ant1	5785	16.480	5776.680	5793.160	0.5	PASS
11A	Ant1	5825	16.360	5816.760	5833.120	0.5	PASS
11N20SISO	Ant1	5745	17.680	5736.120	5753.800	0.5	PASS
11N20SISO	Ant1	5785	17.720	5776.080	5793.800	0.5	PASS
11N20SISO	Ant1	5825	17.720	5816.080	5833.800	0.5	PASS
11N40SISO	Ant1	5755	36.080	5736.760	5772.840	0.5	PASS
11N40SISO	Ant1	5795	36.000	5776.760	5812.760	0.5	PASS
11AC20SISO	Ant1	5745	17.800	5736.040	5753.840	0.5	PASS
11AC20SISO	Ant1	5785	17.720	5776.040	5793.760	0.5	PASS
11AC20SISO	Ant1	5825	17.680	5816.120	5833.800	0.5	PASS
11AC40SISO	Ant1	5755	36.400	5736.760	5773.160	0.5	PASS
11AC40SISO	Ant1	5795	36.080	5776.760	5812.840	0.5	PASS
11AX20SISO	Ant1	5745	18.720	5735.600	5754.320	0.5	PASS
11AX20SISO	Ant1	5785	18.360	5775.600	5793.960	0.5	PASS
11AX20SISO	Ant1	5825	18.520	5815.520	5834.040	0.5	PASS
11AX40SISO	Ant1	5755	36.800	5736.440	5773.240	0.5	PASS
11AX40SISO	Ant1	5795	36.560	5776.280	5812.840	0.5	PASS

Test Graphs B4







Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com








Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com











Appendix B: Duty Cycle

Test Result

Test Mode	Antenna	Frequency[MHz]	Transmission Duration [ms]	Transmission Period [ms]	Duty Cycle [%]	Dc Factor [dB]	1/T
11A	Ant1	5180	5.48	5.55	98.74	0.06	0.18
11A	Ant1	5220	5.48	5.56	98.56	0.06	0.18
11A	Ant1	5240	5.48	5.56	98.56	0.06	0.18
11A	Ant1	5260	5.48	5.55	98.74	0.06	0.18
11A	Ant1	5300	5.48	5.55	98.74	0.06	0.18
11A	Ant1	5320	5.48	5.56	98.56	0.06	0.18
11A	Ant1	5500	5.48	5.55	98.74	0.06	0.18
11A	Ant1	5580	5.48	5.55	98.74	0.06	0.18
11A	Ant1	5700	5.48	5.55	98.74	0.06	0.18
11A	Ant1	5745	5.48	5.56	98.56	0.06	0.18
11A	Ant1	5785	5.48	5.55	98.74	0.06	0.18
11A	Ant1	5825	5.48	5.55	98.74	0.06	0.18
11N20SISO	Ant1	5180	2.50	2.57	97.28	0.12	0.40
11N20SISO	Ant1	5220	2.50	2.57	97.28	0.12	0.40
11N20SISO	Ant1	5240	2.50	2.57	97.28	0.12	0.40
11N20SISO	Ant1	5260	2.50	2.57	97.28	0.12	0.40
11N20SISO	Ant1	5300	2.50	2.57	97.28	0.12	0.40
11N20SISO	Ant1	5320	2.50	2.58	96.90	0.14	0.40
11N20SISO	Ant1	5500	2.51	2.58	97.29	0.12	0.40
11N20SISO	Ant1	5580	2.51	2.58	97.29	0.12	0.40
11N20SISO	Ant1	5700	2.51	2.58	97.29	0.12	0.40
11N20SISO	Ant1	5745	2.51	2.58	97.29	0.12	0.40
11N20SISO	Ant1	5785	2.50	2.58	96.90	0.14	0.40
11N20SISO	Ant1	5825	2.50	2.57	97.28	0.12	0.40
11N40SISO	Ant1	5190	1.22	1.29	94.57	0.24	0.82
11N40SISO	Ant1	5230	1.22	1.30	93.85	0.28	0.82
11N40SISO	Ant1	5270	1.22	1.29	94.57	0.24	0.82
11N40SISO	Ant1	5310	1.22	1.29	94.57	0.24	0.82
11N40SISO	Ant1	5510	1.23	1.30	94.62	0.24	0.81
11N40SISO	Ant1	5550	1.22	1.29	94.57	0.24	0.82
11N40SISO	Ant1	5670	1.22	1.29	94.57	0.24	0.82
11N40SISO	Ant1	5755	1.22	1.30	93.85	0.28	0.82
11N40SISO	Ant1	5795	1.22	1.29	94.57	0.24	0.82
11AC20SISO	Ant1	5180	5.38	5.45	98.72	0.06	0.19
11AC20SISO	Ant1	5220	5.38	5.44	98.90	0.05	0.19
11AC20SISO	Ant1	5240	5.38	5.46	98.53	0.06	0.19


11AC20SISO	Ant1	5260	5.38	5.45	98.72	0.06	0.19
11AC20SISO	Ant1	5300	5.38	5.45	98.72	0.06	0.19
11AC20SISO	Ant1	5320	5.38	5.45	98.72	0.06	0.19
11AC20SISO	Ant1	5500	5.38	5.44	98.90	0.05	0.19
11AC20SISO	Ant1	5580	5.38	5.44	98.90	0.05	0.19
11AC20SISO	Ant1	5700	5.38	5.44	98.90	0.05	0.19
11AC20SISO	Ant1	5745	5.38	5.44	98.90	0.05	0.19
11AC20SISO	Ant1	5785	5.39	5.46	98.72	0.06	0.19
11AC20SISO	Ant1	5825	5.38	5.45	98.72	0.06	0.19
11AC40SISO	Ant1	5190	0.93	1.01	92.08	0.36	1.08
11AC40SISO	Ant1	5230	0.93	1.00	93.00	0.32	1.08
11AC40SISO	Ant1	5270	0.94	1.01	93.07	0.31	1.06
11AC40SISO	Ant1	5310	0.93	1.01	92.08	0.36	1.08
11AC40SISO	Ant1	5510	0.93	1.00	93.00	0.32	1.08
11AC40SISO	Ant1	5550	0.93	1.00	93.00	0.32	1.08
11AC40SISO	Ant1	5670	0.94	1.01	93.07	0.31	1.06
11AC40SISO	Ant1	5755	0.93	1.01	92.08	0.36	1.08
11AC40SISO	Ant1	5795	0.93	1.01	92.08	0.36	1.08
11AX20SISO	Ant1	5180	1.17	1.24	94.35	0.25	0.85
11AX20SISO	Ant1	5220	1.17	1.25	93.60	0.29	0.85
11AX20SISO	Ant1	5240	1.18	1.25	94.40	0.25	0.85
11AX20SISO	Ant1	5260	1.18	1.25	94.40	0.25	0.85
11AX20SISO	Ant1	5300	1.18	1.25	94.40	0.25	0.85
11AX20SISO	Ant1	5320	1.17	1.24	94.35	0.25	0.85
11AX20SISO	Ant1	5500	1.18	1.25	94.40	0.25	0.85
11AX20SISO	Ant1	5580	1.17	1.24	94.35	0.25	0.85
11AX20SISO	Ant1	5700	1.18	1.25	94.40	0.25	0.85
11AX20SISO	Ant1	5745	1.17	1.25	93.60	0.29	0.85
11AX20SISO	Ant1	5785	1.17	1.24	94.35	0.25	0.85
11AX20SISO	Ant1	5825	1.17	1.24	94.35	0.25	0.85
11AX40SISO	Ant1	5190	0.62	0.69	89.86	0.46	1.61
11AX40SISO	Ant1	5230	0.62	0.69	89.86	0.46	1.61
11AX40SISO	Ant1	5270	0.61	0.69	88.41	0.53	1.64
11AX40SISO	Ant1	5310	0.62	0.69	89.86	0.46	1.61
11AX40SISO	Ant1	5510	0.62	0.69	89.86	0.46	1.61
11AX40SISO	Ant1	5550	0.62	0.69	89.86	0.46	1.61
11AX40SISO	Ant1	5670	0.61	0.69	88.41	0.53	1.64
11AX40SISO	Ant1	5755	0.62	0.69	89.86	0.46	1.61
11AX40SISO	Ant1	5795	0.62	0.70	88.57	0.53	1.61

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Test Graphs



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com








Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com















Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com








Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

















Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





























Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com








Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix C: Maximum Conducted Output Power

Test Result Channel Power

Test Mode	Antenna	Frequency[MHz]	Channel Power [dBm]	Duty Cycle [%]	DC Factor [dB]	Result [dBm]	Limit [dBm]	Verdict
11A	Ant1	5180	14.22	98.74	0.06	14.28	≤23.98	PASS
11A	Ant1	5220	13.80	98.56	0.06	13.86	≤23.98	PASS
11A	Ant1	5240	13.34	98.56	0.06	13.40	≤23.98	PASS
11A	Ant1	5260	12.94	98.74	0.06	13.00	≤23.98	PASS
11A	Ant1	5300	12.41	98.74	0.06	12.47	≤23.98	PASS
11A	Ant1	5320	12.44	98.56	0.06	12.50	≤23.94	PASS
11A	Ant1	5500	14.83	98.74	0.06	14.89	≤23.98	PASS
11A	Ant1	5580	14.47	98.74	0.06	14.53	≤23.98	PASS
11A	Ant1	5700	13.55	98.74	0.06	13.61	≤23.98	PASS
11A	Ant1	5745	12.65	98.56	0.06	12.71	≤30.00	PASS
11A	Ant1	5785	12.92	98.74	0.06	12.98	≤30.00	PASS
11A	Ant1	5825	12.74	98.74	0.06	12.80	≤30.00	PASS
11N20SISO	Ant1	5180	15.20	97.28	0.12	15.32	≤23.98	PASS
11N20SISO	Ant1	5220	14.54	97.28	0.12	14.66	≤23.98	PASS
11N20SISO	Ant1	5240	14.01	97.28	0.12	14.13	≤23.98	PASS
11N20SISO	Ant1	5260	13.62	97.28	0.12	13.74	≤23.98	PASS
11N20SISO	Ant1	5300	12.93	97.28	0.12	13.05	≤23.98	PASS
11N20SISO	Ant1	5320	12.82	96.90	0.14	12.96	≤23.98	PASS
11N20SISO	Ant1	5500	15.25	97.29	0.12	15.37	≤23.98	PASS
11N20SISO	Ant1	5580	15.00	97.29	0.12	15.12	≤23.98	PASS
11N20SISO	Ant1	5700	13.96	97.29	0.12	14.08	≤23.98	PASS
11N20SISO	Ant1	5745	13.09	97.29	0.12	13.21	≤30.00	PASS
11N20SISO	Ant1	5785	13.46	96.90	0.14	13.60	≤30.00	PASS
11N20SISO	Ant1	5825	13.07	97.28	0.12	13.19	≤30.00	PASS
11N40SISO	Ant1	5190	14.71	94.57	0.24	14.95	≤23.98	PASS
11N40SISO	Ant1	5230	13.70	93.85	0.28	13.98	≤23.98	PASS
11N40SISO	Ant1	5270	13.63	94.57	0.24	13.87	≤23.98	PASS
11N40SISO	Ant1	5310	13.21	94.57	0.24	13.45	≤23.98	PASS
11N40SISO	Ant1	5510	15.42	94.62	0.24	15.66	≤23.98	PASS
11N40SISO	Ant1	5550	15.93	94.57	0.24	16.17	≤23.98	PASS
11N40SISO	Ant1	5670	14.00	94.57	0.24	14.24	≤23.98	PASS
11N40SISO	Ant1	5755	13.05	93.85	0.28	13.33	≤30.00	PASS
11N40SISO	Ant1	5795	13.44	94.57	0.24	13.68	≤30.00	PASS
11AC20SISO	Ant1	5180	13.98	98.72	0.06	14.04	≤23.98	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AC20SISO	Ant1	5220	13.51	98.90	0.05	13.56	≤23.98	PASS
11AC20SISO	Ant1	5240	12.67	98.53	0.06	12.73	≤23.98	PASS
11AC20SISO	Ant1	5260	12.02	98.72	0.06	12.08	≤23.98	PASS
11AC20SISO	Ant1	5300	11.30	98.72	0.06	11.36	≤23.98	PASS
11AC20SISO	Ant1	5320	11.06	98.72	0.06	11.12	≤23.98	PASS
11AC20SISO	Ant1	5500	14.11	98.90	0.05	14.16	≤23.98	PASS
11AC20SISO	Ant1	5580	13.62	98.90	0.05	13.67	≤23.98	PASS
11AC20SISO	Ant1	5700	12.67	98.90	0.05	12.72	≤23.98	PASS
11AC20SISO	Ant1	5745	11.78	98.90	0.05	11.83	≤30.00	PASS
11AC20SISO	Ant1	5785	11.99	98.72	0.06	12.05	≤30.00	PASS
11AC20SISO	Ant1	5825	11.93	98.72	0.06	11.99	≤30.00	PASS
11AC40SISO	Ant1	5190	14.48	92.08	0.36	14.84	≤23.98	PASS
11AC40SISO	Ant1	5230	13.67	93.00	0.32	13.99	≤23.98	PASS
11AC40SISO	Ant1	5270	13.60	93.07	0.31	13.91	≤23.98	PASS
11AC40SISO	Ant1	5310	13.08	92.08	0.36	13.44	≤23.98	PASS
11AC40SISO	Ant1	5510	15.45	93.00	0.32	15.77	≤23.98	PASS
11AC40SISO	Ant1	5550	15.92	93.00	0.32	16.24	≤23.98	PASS
11AC40SISO	Ant1	5670	13.98	93.07	0.31	14.29	≤23.98	PASS
11AC40SISO	Ant1	5755	13.02	92.08	0.36	13.38	≤30.00	PASS
11AC40SISO	Ant1	5795	13.52	92.08	0.36	13.88	≤30.00	PASS
11AX20SISO	Ant1	5180	15.21	94.35	0.25	15.46	≤23.98	PASS
11AX20SISO	Ant1	5220	14.87	93.60	0.29	15.16	≤23.98	PASS
11AX20SISO	Ant1	5240	14.23	94.40	0.25	14.48	≤23.98	PASS
11AX20SISO	Ant1	5260	13.72	94.40	0.25	13.97	≤23.98	PASS
11AX20SISO	Ant1	5300	13.10	94.40	0.25	13.35	≤23.98	PASS
11AX20SISO	Ant1	5320	13.21	94.35	0.25	13.46	≤23.98	PASS
11AX20SISO	Ant1	5500	15.64	94.40	0.25	15.89	≤23.98	PASS
11AX20SISO	Ant1	5580	15.26	94.35	0.25	15.51	≤23.98	PASS
11AX20SISO	Ant1	5700	14.41	94.40	0.25	14.66	≤23.98	PASS
11AX20SISO	Ant1	5745	13.44	93.60	0.29	13.73	≤30.00	PASS
11AX20SISO	Ant1	5785	13.52	94.35	0.25	13.77	≤30.00	PASS
11AX20SISO	Ant1	5825	13.46	94.35	0.25	13.71	≤30.00	PASS
11AX40SISO	Ant1	5190	15.34	89.86	0.46	15.80	≤23.98	PASS
11AX40SISO	Ant1	5230	14.03	89.86	0.46	14.49	≤23.98	PASS
11AX40SISO	Ant1	5270	14.00	88.41	0.53	14.53	≤23.98	PASS
11AX40SISO	Ant1	5310	13.50	89.86	0.46	13.96	≤23.98	PASS
11AX40SISO	Ant1	5510	15.99	89.86	0.46	16.45	≤23.98	PASS
11AX40SISO	Ant1	5550	16.29	89.86	0.46	16.75	≤23.98	PASS
11AX40SISO	Ant1	5670	14.11	88.41	0.53	14.64	≤23.98	PASS
11AX40SISO	Ant1	5755	13.27	89.86	0.46	13.73	≤30.00	PASS
11AX40SISO	Ant1	5795	13.84	88.57	0.53	14.37	≤30.00	PASS


Note: 1.The Duty Cycle Factor and cable loss are compensated in the graph.

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Test Graphs Channel Power





Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com










Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com






Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

