

3390 East Harmony Road
Fort Collins
Colorado 80528
United States



FCC Laboratory
7435 Oakland Mills Rd.
Columbia, MD 21046

To whom it may concern:

This device with FCC ID: B94HNI65CKLR integrates a WWAN module:

	FCC ID	Grant Date
5G Module	2AX2URW350RGL	06/20/2024

No hardware design changes are made on the modules, and the software has not been changed to increase the RF output power of the modules. Pursuant to KDB 996369 D02 v02r02, the original modular report as following are submitted to represent the compliance of Part 22/24/27/90/96 conducted RF testing items of this device.

Report Number				
FG430728A	FG430728B	FG430728C	FG430728D	FG430728E
FG430728F	FG430728G	FG430728H	FG430728I	FG430728J
FG430728K	FG430728L	FG430728M	FG430728N	FG430728O
FG430728P	FG430728Q	FG430728R	FG430728S	FG430728T
FG430728U				

The radiated RF testing items are tested on this host device, and the test report is submitted additionally.

Sincerely,

A handwritten signature in black ink that reads 'Liang Rong Chiao'.

Liang Rong Chiao

Worldwide Technical Regulations
HP International Pte. Ltd., Taiwan Branch
10F-1, No. 66, Jingmao 2nd Road, Nangang District, Taipei 11568. Taiwan
frances.liang@hp.com
T +886-2-37892469