







CAUTION This device is to be serviced only by properly qualified service personnel. Consult the service manual for proper service and safety to ensure compliance with the Federal Performance Standard for Microwave Ovens and for proper safety to be taken to avoid possible exposure to excessive microwave energy.

WARNING TO ENSURE CONTINUOUS PROTECTION AGAINST EXISTING HAZARDOUS CURRENTS TO PERSONS, DISCONNECT THIS UNIT FROM THE ELECTRICAL SUPPLY BEFORE REPAIRING OR MAINTENANCE OF THE UNIT. DISCONNECT THE UNIT FROM THE ELECTRICAL SUPPLY TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.

WARNING CERTAIN INTERNAL PARTS ARE EXTREMELY HOT DURING NORMAL OPERATION. DO NOT TOUCH THE INTERNAL PARTS WHILE THE APPLIANCE IS OPERATING. THE MICROWAVE ENERGY TRANSMISSION FROM THE CONTROL PANEL, TUBES & THERMISTORS MAY BE HARMFUL TO HUMANS.

WARNING RISK OF ELECTRIC SHOCK. HIGH-VOLTAGE TRANSFORMERS AND INDUCTION HEATING OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE COVERS.

NOT FOR BUILT-IN INSTALLATION

SAMSUNGHOUSEHOLD MICROWAVE OVEN
416 MAETANDONG, SUWON, KOREAMODEL NO.
MW1255WA


SERIAL NO.

120Vac

60Hz

1.65 kW
MICROWAVE

LISTED



725F

725F

MANUFACTURED : FEBRUARY-2001

FCC ID : A3LMW1255

MADE IN KOREA

SEC

THIS PRODUCT COMPLIES WITH DHHS RULES 21 CFR SUBCHAPTER J.

CAUTION THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.

WARNING - TO ENSURE CONTINUED PROTECTION AGAINST ELECTRIC SHOCK HAZARD CONNECT TO PROPERLY GROUNDED OUTLETS ONLY. DISCONNECT APPLIANCE BEFORE SERVICING REMOVAL OF OUTER CASE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS.

WARNING CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDING AND MAY PRESENT A RISK OF ELECTRICAL SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL - DO NOT CONTACT THE HIGH VOLTAGE TRANSFORMER (TROUGH CONTROL TYPE), PAN MOTOR, MAGNETRON BRACKET (MECHANICAL TYPE).

WARNING RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS.

NOT FOR BUILT-IN INSTALLATION

NOT FOR BUILT-IN INSTALLATION

