

Mike Kuo

From: Helen Zhao
Sent: June 21 日 2004 年 Monday 2:03 PM
To: Mike Kuo
Subject: RE: Re : FW: LG Electronics Inc., FCC ID: BEJAD5235, Assessment NO.: AN04T3953



LG-AD5235
echnacal Specificat.



LG-AD5235 SAR
Test Report.pdf



LG-AD5235 User
Manual Revised....

Hello Mike,

Below is the answer to your questions:

Question #1: Only Left/Right head touched and tilted position on channel 363

SAR plots are included in the test report. Please submit all SAR plots for left and right head positions.

<Answer> Please see the revised SAR test report.

Question #2: Please submit rest of body worn SAR plots.

<Answer> Please see the revised SAR test report.

Question #3: The transmitting frequency range listed in the test report does not agree with Channel Vs frequency listed in the technical specification file. Please explain.

<Answer> Please see the revised Technical Specification.

Question #4: Page 15 of user manual, section 2.5.2 Antenna Cable Connection Connect the antenna coupler cable connector from the cradle to the external antenna connector. (Antenna is not included.)

Please explain what type of antenna coupler will be used and how it is connected. Is it connected to the cellular phone ?

<Answer> Section 2.5.2 has been removed from the user manual. See the revised manual.

Thank you,
Helen