






Band5-4132-1-PASS




Band5-4132-2-PASS




Band5-4132-3-PASS




Band5-4132-4-PASS




Band5-4132-5-PASS




Band5-4182-1-PASS




Band5-4182-2-PASS




Band5-4182-3-PASS




Band5-4182-4-PASS




Band5-4182-5-PASS




Band5-4233-1-PASS




Band5-4233-2-PASS



Band5-4233-3-PASS



Band5-4233-4-PASS



Band5-4233-5-PASS

AppendixC:26dB Bandwidth andOccupied Bandwidth

Test Result

Band	Channel	Occupied Bandwidth (MHz)	26dB Bandwidth (MHz)	Limit(MHz)	Verdict
Band5	4132	4.146	4.72	---	PASS
Band5	4182	4.156	4.71	---	PASS
Band5	4233	4.146	4.71	---	PASS

Band	Channel	SubTest	Occupied Bandwidth (MHz)	26dB Bandwidth (MHz)	Limit(MHz)	Verdict
Band5	4132	1	4.156	4.72	---	PASS
Band5	4132	2	4.146	4.72	---	PASS
Band5	4132	3	4.146	4.71	---	PASS
Band5	4132	4	4.156	4.71	---	PASS
Band5	4182	1	4.166	4.73	---	PASS
Band5	4182	2	4.166	4.71	---	PASS
Band5	4182	3	4.166	4.71	---	PASS
Band5	4182	4	4.166	4.72	---	PASS
Band5	4233	1	4.156	4.72	---	PASS
Band5	4233	2	4.156	4.70	---	PASS
Band5	4233	3	4.166	4.72	---	PASS
Band5	4233	4	4.166	4.72	---	PASS

Band	Channel	SubTest	Occupied Bandwidth (MHz)	26dB Bandwidth (MHz)	Limit(MHz)	Verdict
Band5	4132	1	4.176	4.72	---	PASS
Band5	4132	2	4.176	4.72	---	PASS
Band5	4132	3	4.176	4.72	---	PASS
Band5	4132	4	4.176	4.72	---	PASS
Band5	4132	5	4.156	4.70	---	PASS
Band5	4182	1	4.186	4.72	---	PASS
Band5	4182	2	4.196	4.73	---	PASS
Band5	4182	3	4.186	4.72	---	PASS
Band5	4182	4	4.186	4.73	---	PASS
Band5	4182	5	4.176	4.73	---	PASS
Band5	4233	1	4.176	4.72	---	PASS
Band5	4233	2	4.176	4.72	---	PASS

Waltek Testing Group (Shenzhen) Co., Ltd.

[Http://www.waltek.com.cn](http://www.waltek.com.cn)

Band5	4233	3	4.176	4.72	---	PASS
Band5	4233	4	4.176	4.74	---	PASS
Band5	4233	5	4.166	4.71	---	PASS