



Label Location

DynaScan

Model Code : *****

P/N Code : 9G*****

Model Name : **68301**

Rating : **5V - 2.5A**

FCC ID: **2AKWY-XBP501**

IC : **35225-XBP501**

CAN ICES(B)/NMB(B)

S/N Code





CONFORMS TO
UL STD. 62368-1
CERTIFIED TO
CSA STD. C22.2
NO. 62368-1
5022047

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: 1) This device may not cause harmful interference, and 2) this device must accept any interference received, including interference that may cause undesired operation.

DynaScan Technology Corp. 6F, No. 88, Wenmao Rd., Guishan Dist., Taoyuan City 333001, Taiwan



ダイナスキャン
テクノロジー
ジャパン株式会社




Made in Taiwan



Label Location

DynaScan	FCC ID: 2AKWY- XBP501			CONFORMS TO UL STD. 62368-1 CERTIFIED TO CSA STD. C22.2 NO. 62368-1 5022047	
Model Code : *****	IC : 35225-XBP501				
P/N Code : 9G*****	CAN ICES(B)/NMB(B)		Intertek		
Model Name : 68303	S/N Code				
Rating : 5V - 2.5A	*****	     	ダイナスキャン テクノロジー ジャパン株式会社	RoHS	Made in Taiwan
This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: 1) This device may not cause harmful interference, and 2) this device must accept any interference received, including interference that may cause undesired operation.					
DynaScan Technology Corp. 6F, No. 88, Wenmao Rd., Gulshan Dist., Taoyuan City 333001, Taiwan					



Label Location

DynaScan

Model Code : *****

P/N Code : 9G*****

Model Name : **68305**

Rating : **12V = 2.5A**

FCC ID: **2AKWY-XBP501**

IC : **35225-XBP501**

CAN ICES(B)/NMB(B)

S/N Code





Intertek

CONFORMS TO
UL STD. 62368-1
CERTIFIED TO
CSA STD. C22.2
NO. 62368-1
5022047


This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: 1) This device may not cause harmful interference, and 2) this device must accept any interference received, including interference that may cause undesired operation.

DynaScan Technology Corp. 8F, No. 88, Wenmao Rd., Guishan Dist., Taoyuan City 333001, Taiwan



ダイナスキャン
テクノロジー
ジャパン株式会社

RoHS Made in Taiwan



Label Location

DynaScan

Model Code : *****

P/N Code : 9G*****

Model Name : **68307**

Rating : **12V** - **2.5A**

FCC ID: 2AKWY-**XBP501**

IC : **35225-XBP501**

CAN ICES(B)/NMB(B)

S/N Code





CONFORMS TO
UL STD. 62368-1
CERTIFIED TO
CSA STD. C22.2
NO. 62368-1
5022047

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: 1) This device may not cause harmful interference, and 2) this device must accept any interference received, including interference that may cause undesired operation.

DynaScan Technology Corp. 6F, No. 88, Wenmao Rd., Guishan Dist., Taoyuan City 333001, Taiwan



ダイナスキャン
テクノロジー
ジャパン株式会社



Made in Taiwan