



90, Gajaeul-ro, Seo-Gu, Incheon, 22830, Republic of Korea
Tel : 032-580-3862, FAX: 032-580-3159

Attestation Letter

Date: 2025-12-10

FEDERAL COMMUNICATIONS COMMISSION
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Dear Sir or Madam:

Our product AP, model: MCR-AP19000, FCC ID: 2AVW5-MCR-AP19000, for marketing purpose, this product only supports BLE 1M/2M, 2.4G WIFI(2412-2462MHz, 802.11b/g/n ht20/ax he20/be eht20/n ht40/ax he40/be eht40), 5G WIFI(5150-5250MHz, 5250-5350MHz, 5470-5725MHz, 5725-5850MHz, 802.11a/n ht20/ac vht20/ax he20/be eht20/n ht40/ac vht40/ax he40/be eht40/ac vht80/ax he80/be eht80/ac vht160/ax he160/be eht160 modes), WIFI 6E(5925-6425 MHz, 6425-6525 MHz, 6525-6875MHz, 6875-7125 MHz, 802.11ax he20/be eht20/ax he40/be eht40/ax he80/be eht80/ax he160/be eht160 /be eht320 modes). This product also does not support 7115MHz. The other functions, bands and modes was disabled to use by manufacturer in the software, the end user has no capability to activate it.

Sincerely,

A handwritten signature in black ink, appearing to be 'DS' or 'Kim', written in a fluid, cursive style.

DongSeop Kim
Manager
MERCURY Corporation
90, Gajaeul-ro, Seo-Gu, Incheon, 22830, Republic of Korea