



n77h_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3939.99MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3964.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77h_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3915MHz_Outer_Full_Ant1



n77h_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3939.99MHz_Outer_Full_Ant1






Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


3.2.4 30_S_40M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n77h_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3960MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3920.01MHz_Outer_Full_Ant1



n77h_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3939.99MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3960MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


**Radiolink Testing (Shenzhen) Co., Ltd.**

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n77h_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3960MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3920.01MHz_Outer_Full_Ant1



n77h_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3939.99MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3960MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n77h_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3920.01MHz_Outer_Full_Ant1



n77h_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3939.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77h_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3960MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3920.01MHz_Outer_Full_Ant1



n77h_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3939.99MHz_Outer_Full_Ant1



n77h_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3960MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n77h_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3920.01MHz_Outer_Full_Ant1



n77h_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3939.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77h_30kHz_SISO_NTNV_40MHz_CP-OFDM_16 QAM_3960MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_40MHz_CP-OFDM_64 QAM_3920.01MHz_Outer_Full_Ant1



n77h_30kHz_SISO_NTNV_40MHz_CP-OFDM 64 QAM_3939.99MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_40MHz_CP-OFDM 64 QAM_3960MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77h_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3920.01MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3939.99MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694




3.2.5 30_S_50M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77h_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM PI/2 BPSK_3954.99MHz_Outer_Full_Ant1



n77h_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM QPSK_3925.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n77h_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3939.99MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3954.99MHz_Outer_Full_Ant1




**Radiolink Testing (Shenzhen) Co., Ltd.**

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77h_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3954.99MHz_Outer_Full_Ant1



n77h_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3925.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n77h_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3939.99MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3954.99MHz_Outer_Full_Ant1



n77h_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_3925.02MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_3939.99MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77h_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_3954.99MHz_Outer_Full_Ant1




n77h_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_3925.02MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n77h_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_3939.99MHz_Outer_Full_Ant1



n77h_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_3954.99MHz_Outer_Full_Ant1

