




n78a_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_3789.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_20MHz_CP-OFDM_16_QAM_3710.01MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_20MHz_CP-OFDM_16_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_20MHz_CP-OFDM_16_QAM_3789.99MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_20MHz_CP-OFDM_64_QAM_3710.01MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_20MHz_CP-OFDM_64_QAM_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_20MHz_CP-OFDM_64_QAM_3789.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_20MHz_CP-OFDM_256_QAM_3710.01MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_20MHz_CP-OFDM_256_QAM_3750MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


4.2.3 30_S_30M_NTNV



n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_PI/2_BPSK_3784.98MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3715.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_QPSK_3784.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3715.02MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_3784.98MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3715.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_3784.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3715.02MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3784.98MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3715.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3784.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3715.02MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3784.98MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3715.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3784.98MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3715.02MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3784.98MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
 Shenzhen, Guangdong Province, China
 Tel: +86 0755 23080694


4.2.4 30_S_40M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3780MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3720MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3780MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3720MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3780MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3720MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3780MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3720MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3780MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3720MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3780MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3720MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3780MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3720MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3780MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3720MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3780MHz_Outer_Full_Ant1




4.2.5 30_S_50M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_PI/2_BPSK_3774.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3725.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_QPSK_3774.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3725.01MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_3774.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3725.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_3774.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_3725.01MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_3774.99MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_3725.01MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_3774.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_3725.01MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_3774.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_3725.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_3774.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_50MHz_CP-OFDM_256_QAM_3725.01MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_50MHz_CP-OFDM_256_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_50MHz_CP-OFDM_256_QAM_3774.99MHz_Outer_Full_Ant1


**Radiolink Testing (Shenzhen) Co., Ltd.**

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


4.2.6 30_S_60M_NTNV



n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_PI/2_BPSK_3769.98MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_QPSK_3730.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_QPSK_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_QPSK_3769.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_16_QAM_3730.02MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_16_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_16_QAM_3769.98MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_64_QAM_3730.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_64_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_64_QAM_3769.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_256_QAM_3730.02MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_256_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_256_QAM_3769.98MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_QPSK_3730.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_QPSK_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_QPSK_3769.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_16_QAM_3730.02MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_16_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_16_QAM_3769.98MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_64_QAM_3730.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_64_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_64_QAM_3769.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_256_QAM_3730.02MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_60MHz_CP-OFDM_256_QAM_3750MHz_Outer_Full_Ant1






Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

4.2.7 30_S_70M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM PI/2 BPSK_3765MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM QPSK_3735MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_QPSK_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_QPSK_3765MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_16_QAM_3735MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_16_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_16_QAM_3765MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_64_QAM_3735MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_64_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_64_QAM_3765MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_256_QAM_3735MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_256_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_70MHz_DFT-s-OFDM_256_QAM_3765MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_QPSK_3735MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_QPSK_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_QPSK_3765MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_16_QAM_3735MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_16_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM 16 QAM 3765MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM 64 QAM 3735MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_64_QAM_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_64_QAM_3765MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_256_QAM_3735MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_256_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_70MHz_CP-OFDM_256_QAM_3765MHz_Outer_Full_Ant1




4.2.8 30_S_80M_NTNV




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_PI/2_BPSK_3759.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_QPSK_3740.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_QPSK_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_QPSK_3759.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_16_QAM_3740.01MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_16_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_16_QAM_3759.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_64_QAM_3740.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_64_QAM_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_64_QAM_3759.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_256_QAM_3740.01MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_256_QAM_3750MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_80MHz_DFT-s-OFDM_256_QAM_3759.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_QPSK_3740.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_QPSK_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_QPSK_3759.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_16_QAM_3740.01MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_16_QAM_3750MHz_Outer_Full_Ant1


Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_16_QAM_3759.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_64_QAM_3740.01MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_64_QAM_3750MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_64_QAM_3759.99MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_256_QAM_3740.01MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_256_QAM_3750MHz_Outer_Full_Ant1



Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_80MHz_CP-OFDM_256_QAM_3759.99MHz_Outer_Full_Ant1


**Radiolink Testing (Shenzhen) Co., Ltd.**

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694


4.2.9 30_S_90M_NTNV



n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_PI/2_BPSK_3754.98MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_QPSK_3745.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_QPSK_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_QPSK_3754.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_16_QAM_3745.02MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_16_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_16_QAM_3754.98MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_64_QAM_3745.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_64_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_64_QAM_3754.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_256_QAM_3745.02MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_256_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_90MHz_DFT-s-OFDM_256_QAM_3754.98MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_90MHz_CP-OFDM_QPSK_3745.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_90MHz_CP-OFDM_QPSK_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_90MHz_CP-OFDM_QPSK_3754.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694


n78a_30kHz_SISO_NTNV_90MHz_CP-OFDM_16_QAM_3745.02MHz_Outer_Full_Ant1




n78a_30kHz_SISO_NTNV_90MHz_CP-OFDM_16_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_90MHz_CP-OFDM_16_QAM_3754.98MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_90MHz_CP-OFDM_64_QAM_3745.02MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China

Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_90MHz_CP-OFDM_64_QAM_3750MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_90MHz_CP-OFDM_64_QAM_3754.98MHz_Outer_Full_Ant1




Radiolink Testing (Shenzhen) Co., Ltd.


Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District, Shenzhen, Guangdong Province, China


Tel: +86 0755 23080694

n78a_30kHz_SISO_NTNV_90MHz_CP-OFDM_256_QAM_3745.02MHz_Outer_Full_Ant1



n78a_30kHz_SISO_NTNV_90MHz_CP-OFDM_256_QAM_3750MHz_Outer_Full_Ant1





Radiolink Testing (Shenzhen) Co., Ltd.

Room 103, Building B, Jinghang Industrial Park, Area 71, Xingdong Community, Xin'an Subdistrict, Bao'an District,
Shenzhen, Guangdong Province, China
Tel: +86 0755 23080694