




802.11a\_5845MHz\_Chain 0




802.11a\_5865MHz\_Chain 0




802.11a\_5885MHz\_Chain 0




802.11a\_5845MHz\_Chain 1




802.11a\_5865MHz\_Chain 1



802.11a\_5885MHz\_Chain 1




802.11a\_5845MHz\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 20:57:11

802.11a\_5865MHz\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 20:57:39

802.11a\_5885MHz\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 20:58:09

802.11ac20\_5845MHz\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 31.OCT.2025 13:31:49

802.11ac20\_5865MHz\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 31.OCT.2025 13:33:13

802.11ac20\_5885MHz\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 31.OCT.2025 13:33:49

802.11ac20\_5845MHz\_Chain 1




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 31.OCT.2025 13:37:46

802.11ac20\_5865MHz\_Chain 1




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 31.OCT.2025 13:38:40

802.11ac20\_5885MHz\_Chain 1




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 31.OCT.2025 13:39:14

802.11ac20\_5845MHz\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 31.OCT.2025 13:43:57

802.11ac20\_5865MHz\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 31.OCT.2025 13:44:27

802.11ac20\_5885MHz\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 31.OCT.2025 13:44:57

802.11ac40\_5835MHz\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:34:04

802.11ac40\_5875MHz\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:34:35

802.11ac40\_5835MHz\_Chain 1




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:51:30

802.11ac40\_5875MHz\_Chain 1




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:51:52

802.11ac40\_5835MHz\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:11:08

802.11ac40\_5875MHz\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:11:51

802.11ac80\_5855MHz\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:35:33

802.11ac80\_5855MHz\_Chain 1




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:52:31

802.11ac80\_5855MHz\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:12:36

802.11ac160\_5815MHz\_RU\_FULL\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:36:24

802.11ac160\_5815MHz\_RU\_FULL\_Chain 1




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:53:27

802.11ac160\_5815MHz\_RU\_FULL\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:13:24

802.11ax20\_5845MHz\_RU\_FULL\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaaster Liang  
Date: 31.OCT.2025 13:27:09

802.11ax20\_5865MHz\_RU\_FULL\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaaster Liang  
Date: 31.OCT.2025 13:30:21

802.11ax20\_5885MHz\_RU\_FULL\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaaster Liang  
Date: 31.OCT.2025 13:30:55

802.11ax20\_5845MHz\_RU\_FULL\_Chain 1




ProjectNo.:2501X39127E-RF Tester:Kungfumaaster Liang  
Date: 31.OCT.2025 13:35:44

802.11ax20\_5865MHz\_RU\_FULL\_Chain 1




ProjectNo.:2501X39127E-RF Tester:Kungfumaaster Liang  
Date: 31.OCT.2025 13:36:15

802.11ax20\_5885MHz\_RU\_FULL\_Chain 1




ProjectNo.:2501X39127E-RF Tester:Kungfumaaster Liang  
Date: 31.OCT.2025 13:36:41

802.11ax20\_5845MHz\_RU\_FULL\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 31.OCT.2025 13:42:00

802.11ax20\_5865MHz\_RU\_FULL\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 31.OCT.2025 13:42:31

802.11ax20\_5885MHz\_RU\_FULL\_Chain 2




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 31.OCT.2025 13:43:01

802.11ax40\_5835MHz\_RU\_FULL\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:28:06

802.11ax40\_5875MHz\_RU\_FULL\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:28:38

802.11ax40\_5835MHz\_RU\_FULL\_Chain 1




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:46:42


802.11ax40\_5875MHz\_RU\_FULL\_Chain 1




802.11ax40\_5835MHz\_RU\_FULL\_Chain 2




802.11ax40\_5875MHz\_RU\_FULL\_Chain 2




802.11ax80\_5855MHz\_RU\_FULL\_Chain 0




802.11ax80\_5855MHz\_RU\_FULL\_Chain 1



802.11ax80\_5855MHz\_RU\_FULL\_Chain 2




802.11ax160\_5815MHz\_RU\_FULL\_Chain 0




ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:30:59

802.11ax160\_5815MHz\_RU\_FULL\_Chain 1



ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:49:08

802.11ax160\_5815MHz\_RU\_FULL\_Chain 2



ProjectNo.:2501X39127E-RF Tester:Kungfumaater Liang  
Date: 23.OCT.2025 21:07:54